

# VILLAGE OF CARROLLTON

## IRON / MANGANESE TESTING

2/6/2024

| TESTING LOCATION            | CHL |    | I       | M    |
|-----------------------------|-----|----|---------|------|
| TREATMENT PLANT             | 1.3 | .1 | 0.00    | 0.02 |
| COURTVIEW DR                | 0.9 | .3 | 0.00    | 0.02 |
| 2ND ST SE                   | 1.0 | .2 | 0.00    | 0.02 |
| CANTON RD                   | 1.0 | .2 | 0.00    | 0.03 |
| 12TH ST                     | 1.1 | .3 | 0.00    | 0.02 |
| SECONDARY MCL FOR IRON      |     |    | .3 ppm  |      |
| SECONDARY MCL FOR MANGANESE |     |    | .05 ppm |      |